

Central locking system self-diagnosis 07.96 ä

Standard coding for vehicles > 06.97

Standard code = 10184

The standard code is the sum total of the following:		
- Radio remote control is activated	+	8192
- Horn sounds on activation of anti-theft alarm	+	1024
- Hazard warning lights flash on closing/locking via radio remote control	+	512
- Tailgate/boot lid logic (ATW)	+	256
- Dynamic actuation of interior scanning system	+	128
- Comfort closing/locking via radio remote control	+	64
- Anti-theft alarm (ATW) is activated	+	8
Total (Code):	=	10184