

Thursday,08,March,2018,16:02:21:41134

VCDS -- Windows Based VAG/VAS Emulator Running on Windows XP x86

VCDS Version: 18.2.0.3 HEX-NET CB: 0.4411.4

Data version: 20180212 DS287.0

www.Ross-Tech.com

VIN: WAUGM34D9XN000736 License Plate: TDK 901

Mileage: 158730km-98630mi Repair Order:

Chassis Type: 4D (4D - Audi A8 D2 (1994 > 2003))

Scan: 25 01 03 08 11 15 16 17 18 35 37 45 55 56 57 65 67 75 76 77
02

VIN: WAUGM34D9XN000736 Mileage: 158730km-98630miles

Address 25: Immobilizer Labels: 4B0-953-234.lbl

Part No: 4B0 953 234

Component: IMMO AUZ9Z0H6037700 D03

Coding: 00000

Shop #: WSC 00050

VCID: 608C724FE2E30D4478-5160

1 Fault Found:

01176 - Key

07-10 - Signal too Low - Intermittent

Address 01: Engine Labels: Redir Fail!

Part No: 4D0 907 557 N

Component: 4.2L V8/4V MOTR AT D01

Coding: 04373

Shop #: WSC 02324

VCID: 373EF91317ED2AFCE9-4B1E

1 Fault Found:

01183 - Warning Light for Catalyst Monitoring (K72)

31-00 - Open or Short to Ground

Readiness: N/A

Address 03: ABS Brakes Labels: 8D0-907-389.lbl
Part No: 4D0 907 389
Component: ABS/FDR Allrad D32
Shop #: BB 34612
VCID: 6C94167F1E2B5924D4-51CE

No fault code found.

Address 08: Auto HVAC Labels: Redir Fail!
Part No: 4D0 820 043 K
Component: D2-KLIMAVOLLAUTOMAT D05
Coding: 00080
Shop #: WSC 02324
VCID: 24043E5FB67B51645C-2568

1 Fault Found:
01274 - Air Flow Flap Positioning Motor (V71)
41-10 - Blocked or No Voltage - Intermittent

Address 15: Airbags Labels: 4D0-959-655-AI7.lbl
Part No: 4D0 959 655 H
Component: Airbag 7 Audi 050C
Coding: 00225
Shop #: WSC 02324
VCID: 373EF91317ED2AFCE9-5118

No fault code found.